

AT2000 REM401 I/O card replacement

The production of the REM401 I/O card has been discontinued, so a retrofit replacement is needed.

We recommend that you implement this retrofit in due time, as a defective REM401 module will leave your vessel out of service until the retrofit has been performed. Being proactive and retrofitting before any breakdown, will save you time and money.

Retrofitting the PCS REM401 I/O modules with the new I/O modules is unfortunately not a plug-and-play solution.

You need an upgrade of the CPU as well, and therefore we have made a complete retrofit package.

Installing the new REM401 upgrade package requires an Everllence superintendent with expert knowledge of the system. If you have any maintenance planned in the near future, it would be preferable to order the REM401 upgrade package and have the superintendent install this when on board already.

Please contact your Everllence PrimeServ office for more details.



Everllence

PrimeServ

AT2000 REM401 I/O card replacement

Protect your fleet from downtime with updated I/O cards

Key benefits

- Order now, install when convenient
- Fast (1 day) installation
- Avoid loss of system features
- Upgraded control software
- Calibration of propulsion control system included
- Health check of the propulsion system included

Scope of supply

- I/O module and CPU chip
- Programming of software
- Installation and loading of software.

Applicable to

Applicable for AT2000
Propulsion Control System

More information

Contact your local Everllence PrimeServ office for more information about the product and how the upgrade can improve your propulsion configuration.

Everllence PrimeServ

Niels Juels Vej 15
9900 Frederikshavn, Denmark
RetrofitDK@everllence.com
www.everllence.com/services

